DAVID HAZEKAMP contributed this document.
He found it in his 1966 Thunderbird Hardtop which is RN 61251.

Quality Control Inspection Report

INSPECTOR 16 TELAUTO	RADIO STEREO TAPE ANTENNA	ELECTRICAL AND VACUUM INTERIOR LIGHTS 54 COURTESY CLUSTER	EXTERIOR LIGHTS
HEATER–A/C	POWER WINDOWS L DOOR R L QUARTER R	SAFETY SWITCH	POWER SEAT SEAT BELT
SWITCHES	SPEED CONTROL FUNCTIONAL OK	WINDSHIELD WASHER	GAUGES AMP OIL TEMPERATURE
UNIFLOW 93	VACUUM DOOR LOCK T/S F/S 54	PARKING BRAKE 93	VACUUM DECK LOCK
INSPECTOR 28 TELAUTO	LINE 3 L DOOR TRIM PANEL R	L QTR TRIM PANEL R	LUGGAGE COMPARTMENT TRIM 8
EXTERIOR MOULDINGS	CLOCK HOUSING	GLOVE BOX	PACKAGE TRAY MOULDINGS EXTENSIONS
INTERIOR MOULDINGS ROOF RAIL BACKLITE 8	DECK LID W/STRIP	FINAL O.K. TRIM RADIO ACCESSORY PANEL	DECK LID MARGIN FLUSH TORSION BARS
AIR CONTROL	I.B. MOULDINGS 8	8	
8	8		
			CONVERTIBLE PRE-TRIM BUY-OFF

AAD–10046–WIX REV. 8/65	PAINT DAMAGE RECORD		
LINE 1	LINE 2	LINE 3	REPAIR HOLE
PAINT ACCEPTANCE DATE 6-3	THUNDERBIRD TRIM RECORD PRIMARY KEY NO. 0856	SECONDARY KEY NO.	SERIAL NO. MODEL 132073
INSPECTOR 26 TELAUTO	DOOR LOCK LINE 1 REMOTE	24 9086	L VENT WINDOW R
DRAIN TUBES 24 9086	HEATER–A/C 24 LINE OK PLATE	BRAKE ASSEMBLY 20 PARKING	L DOOR GLASS R 24
GLASS REGULATOR 24 9086 DOOR QUARTER	OUTSIDE MIRROR 24 9086	AIR DUCT 24 9086	L QUARTER GLASS R 24
DOOR WEATHERSTRIP 24 9086	EXTERIOR MOULDINGS R 24 9086	24 9086	L DOOR FIT R
INSPECTOR 18	EXTERIOR MOULDINGS LINE 2	COWL GRILLE 20 9086	UNIFLOW GRILLE 20 9086
INSTRUMENT BOARD	CONSOLE	HEATER–A/C CONTROLS 20 9086	STEERING COLUMN 16
L ROOF SIDE PANELS R 20 9086	CONSOLE MOULDINGS LINE OK	SUN VISORS	STEERING COLUMN DOORS
HEADLINING WRINKLED DAMAGED	INTERIOR MOULDINGS	SPEED CONTROL	L HOOD HINGE R
WARNING LIGHT PANEL		20 9086	20 9086